File Original and First Copy with Department of Ecology Second Copy — Owner's Copy	ELL REPORT WASHINGTON 22/37 Permit No.	3 R 527
	WASHINGTON 22/37 Permit No.	
(1) OWNER: Name CIVE !! HTS Community Club		
(2) LOCATION OF WELL: County /SLAND Bearing and distance from section or subdivision corner /800 FT S		RZEWM.
(3) PROPOSED USE: Domestic Maintenal Municipal	(10) WELL LOG:	
Irrigation Test Well Other	Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.	
(4) TYPE OF WORK: Owner's number of well (if more than one)	MATERIAL FROM	
New well M Method: Dug 🗀 Bored 🗆 Deepened 🗀 Cable 🗀 Driven 🗀	SANDY CLAY 12'	12
Reconditioned Rotary V Jetted	SAND 27"	39
(5) DIMENSIONS: Diameter of well 6 inches	SANDY CLAY 44	7 03
Drilled //2/2 ft. Depth of completed well //2 /2 ft.	BLUE CLHY	23
	COLI MAN	105
(6) CONSTRUCTION DETAILS:	MARCO SALID 1%	"112 K
Casing installed: 6 "Diam from 0 ft. to 07 ft.	CIPIL	KABWY
Threaded [] Diam. from ft. to ft.	5019	
Welded Diam. Trom ft. to ft. to ft.		
Perforations: Yes No		
Type of perforator used		
SIZE of perforations in. by in. perforations from ft. to ft.		
perforations from		
perforations from ft. to ft.		
Caracana		-
Screens: Yes O No Cack		
Type 5407 Model No.		
Diam. Slot size 60 from 0712 ft. to 112/ett.		
Diam. Slot size from ft, to ft.		
Gravel packed: Yes No Size of gravel:		
Gravel placed fromft. toft.		
Surface seal: Yes No No To what depth? ft.		
Material used in seal		
Type of water? Depth of strata		
Method of sealing strata off		
IN DUMP. BERKELU		
(7) PUMP: Manufacturer's Name SERKELY Type: Effet Summer Sint HP 1/2		
(8) WATER LEVELS: Land-surface elevation 2 50 ft.		
Static level 14/2 ft. below top of well Date 5-18:59		
Artesian pressure		
Artesian water is controlled by (Cap, valve, etc.)	,	
(9) WELL TESTS: Drawdown is amount water level is lowered below static level . And 2.7	11 11 11 55 MAG 2	
TAP	Work started MAR 14 1959. Completed MAR 24	Z, 19.2.7
Was a pump test made? Yes No ☐ If yes, by whom? \\ \(\frac{1}{2} \) \\\ \(\frac{1}{2} \) \\ \(\frac{1}{2} \) \\\ \(\frac{1}{2} \) \\\ \(\frac{1}{2} \)		
0 0	This well was drilled under my jurisdiction and th	nis report is
и и и	true to the best of my knowledge and belief.	
Recovery data (time taken as zero when pump turned off) (water level	Allana Make Dance See	
measured from well top to water level) Time Water Level Time Water Level Time Water Level	NAME WHIDBE 1 WELL DEALERS (Person, firm, or corporation) (Type o	r nrint)
O 99"	· •	
0:10 94%	Address OAK HARBUR WASH	
	.	
Date of test MH4 15, 1959	[Signed](Well Driller)	
Bailer test gai/min. with with the crawdown after		
Artesian flow	License No Date	, 19
Temperature of water against was a chemical analysis made: 200 [2] 110 [